

Division of Health Service Regulation

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION	(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: HAL060107	(X2) MULTIPLE CONSTRUCTION A. BUILDING: 01 B. WING _____	(X3) DATE SURVEY COMPLETED 09/24/2015
--	--	---	---

NAME OF PROVIDER OR SUPPLIER THE HAVEN IN THE VILLAGE AT CAROLINA P	STREET ADDRESS, CITY, STATE, ZIP CODE 13150 DORMAN ROAD PINEVILLE, NC 28134
---	---

(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETE DATE
C 000	<p>Initial Comments</p> <p>Report of a Biennial Construction Survey by Ed Miller on September 24, 2015.</p> <p>Records indicates that this facility was first licensed on January 1, 1997. Therefore, we are requiring this facility to meet the 1996 Rules for the Licensing of Adult Care Homes and the applicable portions of the 2005 Licensing Rules and the 1996 edition of the North Carolina State Building Code Volume I - General Construction - Section 409 Institutional Occupancy (Group I). Currently licensed as a SIXTY BED SPECIAL CARE UNIT Facility.</p> <p>Physical plant deficiencies were noted which require a plan of correction.</p>	C 000		
C 101	<p>Existing Licensed Fac- No less than '71 Rules</p> <p>SECTION .0300 - PHYSICAL PLANT 10A NCAC 13F .0301 APPLICATION OF PHYSICAL PLANT REQUIREMENTS The physical plant requirements for each adult care home shall be applied as follows: (2) Except where otherwise specified, existing licensed facilities or portions of existing licensed facilities shall meet licensure and code requirements in effect at the time of construction, change in service or bed count, addition, renovation, or alteration; however in no case shall the requirements for any licensed facility where no addition or renovation has been made, be less than those requirements found in the 1971 "Minimum and Desired Standards and Regulations" for "Homes for the Aged and Infirm", copies of which are available at the Division of Health Service Regulation, 701 Barbour Drive, Raleigh, North Carolina, 27603 at no cost;</p>	C 101		

Division of Health Service Regulation
LABORATORY DIRECTOR'S OR PROVIDER/SUPPLIER REPRESENTATIVE'S SIGNATURE _____ TITLE _____ (X6) DATE _____

Division of Health Service Regulation

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION	(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: HAL060107	(X2) MULTIPLE CONSTRUCTION A. BUILDING: 01 B. WING _____	(X3) DATE SURVEY COMPLETED 09/24/2015
--	--	---	---

NAME OF PROVIDER OR SUPPLIER THE HAVEN IN THE VILLAGE AT CAROLINA P	STREET ADDRESS, CITY, STATE, ZIP CODE 13150 DORMAN ROAD PINEVILLE, NC 28134
---	---

(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETE DATE
C 101	Continued From page 1 This Rule is not met as evidenced by: 1. Based on observation, the facility failed to meet the Code requirements in effect at the time of construction by not having all of the required components for doors equipped with Special Locking Arrangements. This could affect all occupants who would need to evacuate through the door(s) if the exit were obstructed. Findings on September 24, 2015: a. The exit doors are equipped with magnetic locks and the emergency release switches requireing a key to operate. Interview with staff in the area revealed that they did not have keys to operate the emergency release. This is not in accordance with the NC State Building Code requirement that if emergency release switches are of the keyed type, all staff responsible for evacuation of the locked unit must carry keys at all times.	C 101		
C 111	Must Have Current San. & Fire Safety Reports SECTION .0300 - PHYSICAL PLANT 10A NCAC 13F .0302 DESIGN AND CONSTRUCTION(f) The facility shall have current sanitation and fire and building safety inspection reports which shall be maintained in the home and available for review. This Rule is not met as evidenced by: 1. Based on record review, interview with Executive Director, and Maintenance Contractor, the facility failed to maintain, a current (completed within the last twelve months) annual inspection report(s) required. This deficiency affects all residents, staff and visitors by not preventing any systems deficiency that may be discovered with annual inspections.	C 111		

Division of Health Service Regulation

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION	(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: HAL060107	(X2) MULTIPLE CONSTRUCTION A. BUILDING: 01 B. WING _____	(X3) DATE SURVEY COMPLETED 09/24/2015
--	--	---	---

NAME OF PROVIDER OR SUPPLIER THE HAVEN IN THE VILLAGE AT CAROLINA P	STREET ADDRESS, CITY, STATE, ZIP CODE 13150 DORMAN ROAD PINEVILLE, NC 28134
---	---

(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETE DATE
C 111	Continued From page 2 Findings on September 24, 2015: a. Records indicate that the last Annual Fire Alarm System Inspection and Testing Report in accordance with NFPA 72 was performed on July 8, 2015. The report listed several deficiencies that must be addressed.	C 111		
C 150	Corridors-Free of equipment and Obstructions SECTION .0300 - PHYSICAL PLANT 10A NCAC 13F .0305 PHYSICAL ENVIRONMENT (g) The requirements for corridors are: (4) Corridors shall be free of all equipment and other obstructions. This Rule is not met as evidenced by: 1. Based on observation, the Building was not maintained in a safe manner by not maintaining a clear unobstructed exit path from the residents' rooms to the outside. This would affect all residents, staff and visitors by obstructing egress during an emergency. Findings on September 24, 2015: a. Between Willington wing and front Building an exit to the courtyard was blocked with a piano stool. b. The six-foot wide corridor was being used for storage of a resident bed near Bedroom 310, c. In Service hall near kitchen, wall mounted mail boxes and other equipment obstructed the six foot wide corridor.	C 150		
C 164	Housekeeping and Furnishings-Clean, Repaired SECTION .0300 - PHYSICAL PLANT 10A NCAC 13F .0306 HOUSEKEEPING AND FURNISHINGS (a) Adult care homes shall:	C 164		

Division of Health Service Regulation

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION	(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: HAL060107	(X2) MULTIPLE CONSTRUCTION A. BUILDING: 01 B. WING _____	(X3) DATE SURVEY COMPLETED 09/24/2015
--	--	---	---

NAME OF PROVIDER OR SUPPLIER THE HAVEN IN THE VILLAGE AT CAROLINA P	STREET ADDRESS, CITY, STATE, ZIP CODE 13150 DORMAN ROAD PINEVILLE, NC 28134
---	---

(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETE DATE
C 164	Continued From page 3 (1) have walls, ceilings, and floors or floor coverings kept clean and in good repair; (2) have no chronic unpleasant odors; (3) have furniture clean and in good repair; (e) This Rule shall apply to new and existing facilities. This Rule is not met as evidenced by: 1. Based on Observation, the facility failed to have furniture kept clean and in good repair. Findings on September 24, 2015: a. In the Activity Room, the built-in counter was missing one of its drawers.	C 164		
C 166	Housekeeping-Maintained Free of Hazards SECTION .0300 - PHYSICAL PLANT 10A NCAC 13F .0306 HOUSEKEEPING AND FURNISHINGS (a) Adult care homes shall: (5) be maintained in an uncluttered, clean and orderly manner, free of all obstructions and hazards; (e) This Rule shall apply to new and existing facilities. This Rule is not met as evidenced by: 1. Based on Observation, the facility failed to provide an environment in accordance with this Rule, by not maintaining the HVAC/ventilation, grilles and their associated dampers free of hazards. This could affect all residents, staff and visitors if in the event of a fire the dampers do not close completely to contain the fire within the room of origin. Findings on September 24, 2015: a. The return HVAC and ventilation grilles and their radiation dampers have an excessive accumulation of dust/lint. Locations of specific	C 166		

Division of Health Service Regulation

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION	(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: HAL060107	(X2) MULTIPLE CONSTRUCTION A. BUILDING: 01 B. WING _____	(X3) DATE SURVEY COMPLETED 09/24/2015
--	--	---	---

NAME OF PROVIDER OR SUPPLIER THE HAVEN IN THE VILLAGE AT CAROLINA P	STREET ADDRESS, CITY, STATE, ZIP CODE 13150 DORMAN ROAD PINEVILLE, NC 28134
---	---

(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETE DATE
C 166	Continued From page 4 examples include but are not limited to: i. Pair of Visitor's Toilet Rooms, near Actively Room, ii. Janitor's Closet near Kitchen, iii. Staff Toilet Room near Kitchen, iv. Therapy	C 166		
C 189	Building Equipment Maintained Safe, Operating SECTION .0300 - PHYSICAL PLANT 10A NCAC 13F .0311 OTHER REQUIREMENTS (a) The building and all fire safety, electrical, mechanical, and plumbing equipment in an adult care home shall be maintained in a safe and operating condition. (k) This Rule shall apply to new and existing facilities with the exception of Paragraph (e) which shall not apply to existing facilities. This Rule is not met as evidenced by: 1. Based on observation, the Building was not maintained in a safe and operating condition, by failing to ensure that egress from all areas can be done without the use of keys, tools or, special knowledge or effort. This could affect some staff and visitors if someone becomes trapped inside. Findings on September 24, 2015: a. The Activity Room's occupant load exceeds 49 persons but there was only one marked exit door. The room also has two pairs of double doors that open onto a courtyard (no exit signs) that had a locked gate. The gate was locked with a breakaway pad lock. 2. Based on observation, the Building was not maintained in a safe and operating condition, because the exit signs did not work or relay	C 189		

Division of Health Service Regulation

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION	(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: HAL060107	(X2) MULTIPLE CONSTRUCTION A. BUILDING: 01 B. WING _____	(X3) DATE SURVEY COMPLETED 09/24/2015
--	--	---	---

NAME OF PROVIDER OR SUPPLIER THE HAVEN IN THE VILLAGE AT CAROLINA P	STREET ADDRESS, CITY, STATE, ZIP CODE 13150 DORMAN ROAD PINEVILLE, NC 28134
---	---

(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETE DATE
C 189	<p>Continued From page 5</p> <p>directional information properly. This would affect all residents, staff and visitors if they could not promptly find their way to an exit during an emergency.</p> <p>Findings on September 24, 2015:</p> <p>a. The exit sign did not work on backup power when tested. Locations of specific examples include but are not limited to:</p> <p>i. Corridor near Bedroom 407,</p> <p>ii. Corridor near Bedroom 410.</p> <p>b. The front door's exit sign had inappropriate chevrons graphics that misrepresent the way to egress from the building during an emergency.</p> <p>c. The exit sign did not work on normal power or backup power when tested in the Therapy Room.</p> <p>3. Based on observation, the Building was not maintained in a safe and operating condition, because the commercial kitchen hood's fire extinguishing system lacked the inspections, maintenance and documented required to ensure a properly working system. This could affect all residents, staff and visitors if the commercial kitchen hood's suppression system fails to operate properly when needed.</p> <p>Findings on September 24, 2015:</p> <p>a. Per the semi-annual maintenance tag, the commercial kitchen hood's fire extinguishing system was last maintained in July of 2014.</p> <p>b. Since the semi-annual maintenance of the commercial kitchen hood's fire extinguishing system in July 2014, there has been no record keeping of the monthly inspections.</p> <p>4. Based on observation, the Building was not maintained in a safe and operating condition, because the electrical power system was not being operated or maintained safely. This would affect all staff, by allowing unsafe conditions to</p>	C 189		

Division of Health Service Regulation

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION	(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: HAL060107	(X2) MULTIPLE CONSTRUCTION A. BUILDING: 01 B. WING _____	(X3) DATE SURVEY COMPLETED 09/24/2015
--	--	---	---

NAME OF PROVIDER OR SUPPLIER THE HAVEN IN THE VILLAGE AT CAROLINA P	STREET ADDRESS, CITY, STATE, ZIP CODE 13150 DORMAN ROAD PINEVILLE, NC 28134
---	---

(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETE DATE
C 189	<p>Continued From page 6</p> <p>persist.</p> <p>Findings on September 24, 2015:</p> <p>a. The electrical panels had open slots were breakers was removed or a blanks fail out at the following locations to include but not limited to:</p> <p>i. Panel Room-Panel LF</p> <p>ii. Service Hall between Wilmington and Charlotte Wing-Panel MA</p> <p>b. In the Freezer the refrigeration equip was missing it cover plate.</p> <p>c. An electrical power receptacle in the Hopper Room between Wilmington and Charlotte was missing a cover plate.</p> <p>5. Based on observation, the Building was not maintained in a safe and operating condition, because the fire sprinkler escutcheon plates were impaired, exposing openings through the ceiling that could allow the passage of smoke and heat. This would affect all residents, staff and visitors, if the fire suppression system does not operate in a timely manner and cannot contained fire in the Room of origin.</p> <p>Findings on September 24, 2015:</p> <p>a. The fire sprinkler escutcheon plate had dropped down from the ceiling. Locations of specific examples include but are not limited to:</p> <p>i. Front Corridor of "B" wing.</p> <p>ii. Housekeeping Room in Service Hall between Ashville and Charlotte wings</p> <p>iii.</p> <p>b. The fire sprinkler escutcheon plate did not cover the complete hole through the ceiling. Locations of specific examples include but are not limited to:</p> <p>i. Porch near Bedroom 310.</p> <p>c. The fire sprinkler escutcheon plate was missing. Locations of specific examples include but are not limited to:</p> <p>i. Third Storage Room from the front in the</p>	C 189		

Division of Health Service Regulation

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION	(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: HAL060107	(X2) MULTIPLE CONSTRUCTION A. BUILDING: 01 B. WING _____	(X3) DATE SURVEY COMPLETED 09/24/2015
--	--	---	---

NAME OF PROVIDER OR SUPPLIER THE HAVEN IN THE VILLAGE AT CAROLINA P	STREET ADDRESS, CITY, STATE, ZIP CODE 13150 DORMAN ROAD PINEVILLE, NC 28134
---	---

(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETE DATE
C 189	<p>Continued From page 7</p> <p>Activity Room.</p> <p>ii. Freezer</p> <p>iii. Housekeeping Room in Service Hall between Wilmington and Charlotte wings.</p> <p>d. The fire sprinkler escutcheon plate and piping had dropped down from the ceiling in the Laundry in Service Hall between Wilmington and Charlotte wings.</p> <p>e. The fire sprinkler head in the kitchen walk-in cooler had orange foam sealing in the parts around the internal escutcheon plate.</p> <p>6. Based on observations, the Building was not maintained in a safe and operating condition, because breaches through the fire-resistance-rated construction invalidated its integrity. This could affect all residents, staff and visitors if smoke/fire is not contained in Room or compartment of origin. Findings on September 24, 2015:</p> <p>a. The ceiling had an unprotected cable penetration through the ceiling assembly right of the Double doors to the Staff Only Area.</p> <p>b. The ceiling had unprotected gap around 1 ½ inch conduits penetration in the Fire Panel Room.</p> <p>c. The fire-resistance-rated ceiling assembly had a 1 ½ inch hole in the First Storage Room from the front in the Activity Room,</p> <p>d. In the Second Storage Room from the front in the Activity Room the attic access door was open at the time of Survey. This is not in conformance with the NC State Building Code, which requires the fire-resistance-rating of the ceiling must be maintained. Deficiency corrected before Construction Surveyors departed Site.</p> <p>e. Most of the new exit light did not completely cover the hole through the fire-resistance-rated ceiling assembly throughout the building.</p> <p>7. Based on observation, the Building was not</p>	C 189		

Division of Health Service Regulation

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION	(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: HAL060107	(X2) MULTIPLE CONSTRUCTION A. BUILDING: 01 B. WING _____	(X3) DATE SURVEY COMPLETED 09/24/2015
--	--	---	---

NAME OF PROVIDER OR SUPPLIER THE HAVEN IN THE VILLAGE AT CAROLINA P	STREET ADDRESS, CITY, STATE, ZIP CODE 13150 DORMAN ROAD PINEVILLE, NC 28134
---	---

(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETE DATE
C 189	<p>Continued From page 8</p> <p>maintained in a safe and operating condition, by not maintaining the fire and smoke resistance of doors the NC State Building Code defines as "Hazardous Area". This could affect all residents, staff and visitors if smoke/fire is not contained in Room or fire compartment of origin.</p> <p>Findings on September 24, 2015:</p> <ol style="list-style-type: none"> a. The Janitor door near Kitchen had duct tape covering strike plate not allowing door to latch. b. The Riser Room had duct tape covering strike plate not allowing door to latch. c. The Kitchen door near Hood suppression Pull, did not close on its own power, <p>8. Based on observation, the Building was not maintained in a safe and operating condition, because the corridor doors did not resist the passage of smoke due to door leafs not fitting into their frames with acceptable gaps under normal closing force. This could affect all residents, staff and visitors if the doors did not contain smoke/fire in the room of origin.</p> <p>Findings on September 24, 2015:</p> <ol style="list-style-type: none"> a. The double doors to the Activity Room do not have astragals to provide a smoke tight seal between the meeting edges of the doors. b. The Nurse Station Dutch door had an open gap between the leaves allowing smoke to pass through. c. The top leave of the Nurse Station Dutch door, did not automatically latch into the bottom leaf <p>9. Based on Observation, the Building was not maintained in a safe and operating condition, because some corridor doors were held open by devices that do not release with a push or pull of the door, preventing the doors from being closed and latched rapidly. This could affect all residents, staff and visitors by not containing</p>	C 189		

Division of Health Service Regulation

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION	(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: HAL060107	(X2) MULTIPLE CONSTRUCTION A. BUILDING: 01 B. WING _____	(X3) DATE SURVEY COMPLETED 09/24/2015
--	--	---	---

NAME OF PROVIDER OR SUPPLIER THE HAVEN IN THE VILLAGE AT CAROLINA P	STREET ADDRESS, CITY, STATE, ZIP CODE 13150 DORMAN ROAD PINEVILLE, NC 28134
---	---

(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETE DATE
C 189	<p>Continued From page 9</p> <p>smoke and fire in the room of origin. Findings on September 24, 2015:</p> <ul style="list-style-type: none"> a. Corridor door to the Kitchen was blocked open with a heavy table, b. The Laundry Room door in service hall between Wilmington and Charlotte Wing had a wedge holding the door open. <p>10. Based on Observation, the Building was not maintained in a safe and operating condition, because the portable medical oxygen cylinders were not being properly handled/stored. This could affect all residents, staff and visitors if cylinders fall, breaking their valves, propelling the cylinder and turning it into a dangerous projectile. Findings on September 24, 2015:</p> <ul style="list-style-type: none"> a. Several portable medical oxygen cylinders were stored standing up in beverage crates not secured to the structure in service area between Ashville and Charlotte Wings. 	C 189		
C 199	<p>Exhaust Ventilation</p> <p>SECTION .0300 - PHYSICAL PLANT 10A NCAC 13F .0311 OTHER REQUIREMENTS</p> <p>(g) The spaces listed in this Paragraph shall be provided with exhaust ventilation at the rate of two cubic feet per minute per square foot. This requirement does not apply to facilities licensed before April 1, 1984, with natural ventilation in these specified spaces:</p> <ul style="list-style-type: none"> (1) soiled linen storage; (2) soil utility room; (3) bathrooms and toilet rooms; (4) housekeeping closets; and (5) laundry area. <p>(k) This Rule shall apply to new and existing facilities with the exception of Paragraph (e)</p>	C 199		

Division of Health Service Regulation

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION	(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: HAL060107	(X2) MULTIPLE CONSTRUCTION A. BUILDING: 01 B. WING _____	(X3) DATE SURVEY COMPLETED 09/24/2015
--	--	---	---

NAME OF PROVIDER OR SUPPLIER THE HAVEN IN THE VILLAGE AT CAROLINA P	STREET ADDRESS, CITY, STATE, ZIP CODE 13150 DORMAN ROAD PINEVILLE, NC 28134
---	---

(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETE DATE
C 199	Continued From page 10 which shall not apply to existing facilities. This Rule is not met as evidenced by: 1. Based on Observation and testing the facility failed to maintain the ventilation system in proper working order. This could affect all residents, staff and visitors by subjecting them to odors. Findings on September 24, 2015: a. The exhaust ventilation was not working. Locations of specific examples include but are not limited to: i. Hopper Room between Wilmington and Charlotte Wings ii. Housekeeping between Wilmington and Charlotte Wings iii. Housekeeping between Ashville and Charlotte Wings	C 199		