

Division of Health Service Regulation

| | | | |
|--|--|---|---|
| STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION | (X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: HAL098027 | (X2) MULTIPLE CONSTRUCTION A. BUILDING: 01 B. WING _____ | (X3) DATE SURVEY COMPLETED 03/15/2016 |
|--|--|---|---|

| | |
|---|---|
| NAME OF PROVIDER OR SUPPLIER WILSON ASSISTED LIVING | STREET ADDRESS, CITY, STATE, ZIP CODE 3501 SENIOR VILLAGE LANE WILSON, NC 27896 |
|---|---|

| (X4) ID PREFIX TAG | SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION) | ID PREFIX TAG | PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY) | (X5) COMPLETE DATE |
|--------------------|---|---------------|---|--------------------|
| C 000 | <p>Initial Comments</p> <p>Report of a Biennial Construction Survey by Ed Miller and Bob Getchell on March 15, 2016.</p> <p>Records indicate this facility was first licensed on April 1, 1985 as a HA. The facility is currently licensed for 88 with a 28 Bed Special Care Unit. Therefore the facility was surveyed for conformance with the applicable portions of the 2005 Rules for Licensing of Adult Care Homes of Seven or More Beds, and applicable portions of the 1978 (Revision 5) Edition, of the North Carolina Building Code(s), Institutional Occupancy, and the 1984 Minimum Standards and Regulations for Homes for the Aged in effect at time of initial licensure.</p> <p>Physical plant deficiencies were noted which require a plan of correction.</p> | C 000 | | |
| C 101 | <p>Existing Licensed Fac- No less than '71 Rules</p> <p>SECTION .0300 - PHYSICAL PLANT 10A NCAC 13F .0301 APPLICATION OF PHYSICAL PLANT REQUIREMENTS The physical plant requirements for each adult care home shall be applied as follows: (2) Except where otherwise specified, existing licensed facilities or portions of existing licensed facilities shall meet licensure and code requirements in effect at the time of construction, change in service or bed count, addition, renovation, or alteration; however in no case shall the requirements for any licensed facility where no addition or renovation has been made, be less than those requirements found in the 1971 "Minimum and Desired Standards and Regulations" for "Homes for the Aged and Infirm", copies of which are available at the Division of Health Service Regulation at no cost;</p> | C 101 | | |

Division of Health Service Regulation
LABORATORY DIRECTOR'S OR PROVIDER/SUPPLIER REPRESENTATIVE'S SIGNATURE _____ TITLE _____ (X6) DATE _____

Division of Health Service Regulation

| | | | |
|--|--|---|---|
| STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION | (X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: HAL098027 | (X2) MULTIPLE CONSTRUCTION A. BUILDING: 01 B. WING _____ | (X3) DATE SURVEY COMPLETED 03/15/2016 |
|--|--|---|---|

| | |
|---|---|
| NAME OF PROVIDER OR SUPPLIER WILSON ASSISTED LIVING | STREET ADDRESS, CITY, STATE, ZIP CODE 3501 SENIOR VILLAGE LANE WILSON, NC 27896 |
|---|---|

| (X4) ID PREFIX TAG | SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION) | ID PREFIX TAG | PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY) | (X5) COMPLETE DATE |
|--------------------|--|---------------|---|--------------------|
|--------------------|--|---------------|---|--------------------|

| | | | | |
|-------|--|-------|--|--|
| C 101 | <p>Continued From page 1</p> <p>This Rule is not met as evidenced by:</p> <ol style="list-style-type: none"> 1. Based on observation and interview with SCU Staff, the facility failed to meet the Code requirements in effect at the time of construction by not having all of the required components or procedures to properly operate locked egress doors/gates. This could affect all occupants who would need to evacuate through these locked door(s)/gate(s). <p>Findings on March 15, 2016:</p> <ol style="list-style-type: none"> a. SCU - the cross-corridor doors separating the SCU and AL units had an emergency release switch (SCU side) that would only release the door while the switch was being depressed. This is not in accordance with the NC State Building Code requirement for an on/off emergency release switch, b. SCU Courtyard - the exit gate from the courtyard was secured with metal keyed padlock. Of the staff responsible for the evacuation only the Med Tech had a key and that key was on a ring with at least fifteen other keys with no markings. Also the courtyard was not large enough to provide a safe area of refuge in the event of a fire so the courtyard gate is a required exit. This is not in accordance with the NC State Building Code requirement that if emergency release switches are of the keyed type, all staff responsible for evacuation of the locked unit must carry keys at all times. Deficiency corrected before Construction Surveyors departed Site by distributing 4 metal keys to SCU Staff. c. SCU Courtyard - the exit gate could only open about 30 degrees of the full 90 degrees required, d. The SCU's master emergency release switch for the special locking system was located in a storage closet in the Living/Dining room. The | C 101 | | |
|-------|--|-------|--|--|

Division of Health Service Regulation

| STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION | | (X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: HAL098027 | (X2) MULTIPLE CONSTRUCTION A. BUILDING: 01 B. WING _____ | (X3) DATE SURVEY COMPLETED 03/15/2016 |
|---|---|---|---|---|
| NAME OF PROVIDER OR SUPPLIER WILSON ASSISTED LIVING | | STREET ADDRESS, CITY, STATE, ZIP CODE 3501 SENIOR VILLAGE LANE WILSON, NC 27896 | | |
| (X4) ID PREFIX TAG | SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION) | ID PREFIX TAG | PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY) | (X5) COMPLETE DATE |
| C 101 | Continued From page 2 switch was under a locked cover that only the Maintenance Tech had a key to. e. The SCU's master emergency release switch for the special locking system was only identified with the words "On Off Switch " and the staff interviewed did not know the function of the switch. f. The SCU's master emergency release switch for the special locking system was located in a storage closet in the Living/Dining room. NC State Building Code requires the master emergency release switch to be at a Nurse's Station. Because the SCU does not have a designated Nurse Station, the master switch should be located at least in a readily accessible location, g. SCU -The special locking system for the SCU unit did not have a wiring diagram and system components location map provided under glass at the fire alarm panel. There was a conflict identified between a door identified as an exit by an exit sign and the design of the special locking system installed on the door. At the ime of survey it was not determined whether or not this exit was a required exit from the AL side. The following issues were noted: h. SCU -the cross-corridor doors separating the SCU and AL did not have an emergency release switch on the AL side. Exit signs direct you to exit thru these doors i. SCU -the cross-corridor doors separating the SCU and AL did not have a master emergency release switch located at a nurse station and identified on the AL side. Exit signs direct you to exit thru these doors | C 101 | | |
| C 160 | Outside Premises-Clean, Safe SECTION .0300 - PHYSICAL PLANT | C 160 | | |

Division of Health Service Regulation

| | | | |
|--|--|---|---|
| STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION | (X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: HAL098027 | (X2) MULTIPLE CONSTRUCTION A. BUILDING: 01 B. WING _____ | (X3) DATE SURVEY COMPLETED 03/15/2016 |
|--|--|---|---|

| | |
|---|---|
| NAME OF PROVIDER OR SUPPLIER WILSON ASSISTED LIVING | STREET ADDRESS, CITY, STATE, ZIP CODE 3501 SENIOR VILLAGE LANE WILSON, NC 27896 |
|---|---|

| (X4) ID PREFIX TAG | SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION) | ID PREFIX TAG | PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY) | (X5) COMPLETE DATE |
|--------------------|--|---------------|---|--------------------|
| C 160 | <p>Continued From page 3</p> <p>10A NCAC 13F .0305 PHYSICAL ENVIRONMENT</p> <p>(m) The requirements for outside premises are:</p> <p>(1) The outside grounds of new and existing facilities shall be maintained in a clean and safe condition;</p> <p>This Rule is not met as evidenced by:</p> <p>1. Based on observation, the outside grounds were not maintained in a clean and safe condition. This could affect all residents, staff and visitors if the grounds are not free of obstructions, tripping hazards or have equipment in disrepair.</p> <p>Findings on March 15, 2016:</p> <p>a. The sidewalk at the Front Porch had a non-sloped, vertical changes in the walking path, creating tripping hazards.</p> | C 160 | | |
| C 164 | <p>Housekeeping and Furnishings-Clean, Repaired</p> <p>SECTION .0300 - PHYSICAL PLANT</p> <p>10A NCAC 13F .0306 HOUSEKEEPING AND FURNISHINGS</p> <p>(a) Adult care homes shall:</p> <p>(1) have walls, ceilings, and floors or floor coverings kept clean and in good repair;</p> <p>(2) have no chronic unpleasant odors;</p> <p>(3) have furniture clean and in good repair;</p> <p>(e) This Rule shall apply to new and existing facilities.</p> <p>This Rule is not met as evidenced by:</p> <p>1. Based on Observation, the facility failed to have walls, ceilings, and floors or floor coverings, kept clean and in good repair.</p> <p>Findings on March 15, 2016:</p> <p>a. SCU - the floors had an excessive build-up of wax/dirt around the doorframes,</p> | C 164 | | |

Division of Health Service Regulation

| | | | |
|--|--|---|---|
| STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION | (X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: HAL098027 | (X2) MULTIPLE CONSTRUCTION A. BUILDING: 01 B. WING _____ | (X3) DATE SURVEY COMPLETED 03/15/2016 |
|--|--|---|---|

| | |
|---|---|
| NAME OF PROVIDER OR SUPPLIER WILSON ASSISTED LIVING | STREET ADDRESS, CITY, STATE, ZIP CODE 3501 SENIOR VILLAGE LANE WILSON, NC 27896 |
|---|---|

| (X4) ID PREFIX TAG | SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION) | ID PREFIX TAG | PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY) | (X5) COMPLETE DATE |
|--------------------|---|---------------|---|--------------------|
| C 164 | <p>Continued From page 4</p> <p>b. Bedroom 112 - the corridor door was very marred up,</p> <p>2. Based on Observation, the facility failed to have walls, ceilings, and floors or floor coverings, kept clean and in good repair. Findings on March 15, 2016:</p> <p>a. Corridor near Bedroom 116 - the carpet was stained,</p> <p>3. Based on Observation, the facility failed to provide an environment in accordance with this Rule. This would affect all residents, staff and visitors by exposing them to, unclean conditions and equipment in disrepair. Findings on March 15, 2016:</p> <p>a. Shared Toilet Room 110/112 - the connection of the commode to the floor was loose, b. Bedroom 106 Toilet Room - the connection of the commode to the floor was loose, c. Bedroom 311 Toilet Room - the connection of the commode to the floor was loose, d. Shower Room near Bedroom 303 - the connection of the commode to the floor was loose, e. Bedroom 302 Toilet Room - the connection of the commode to the floor was loose. f. Bedroom 303 - the commode tank lid was broken,</p> | C 164 | | |
| C 166 | <p>Housekeeping-Maintained Free of Hazards</p> <p>SECTION .0300 - PHYSICAL PLANT 10A NCAC 13F .0306 HOUSEKEEPING AND FURNISHINGS (a) Adult care homes shall: (5) be maintained in an uncluttered, clean and orderly manner, free of all obstructions and hazards;</p> | C 166 | | |

Division of Health Service Regulation

| | | | |
|--|--|---|---|
| STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION | (X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: HAL098027 | (X2) MULTIPLE CONSTRUCTION A. BUILDING: 01 B. WING _____ | (X3) DATE SURVEY COMPLETED 03/15/2016 |
|--|--|---|---|

| | |
|---|---|
| NAME OF PROVIDER OR SUPPLIER WILSON ASSISTED LIVING | STREET ADDRESS, CITY, STATE, ZIP CODE 3501 SENIOR VILLAGE LANE WILSON, NC 27896 |
|---|---|

| (X4) ID PREFIX TAG | SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION) | ID PREFIX TAG | PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY) | (X5) COMPLETE DATE |
|--------------------|---|---------------|---|--------------------|
| C 166 | <p>Continued From page 5</p> <p>(e) This Rule shall apply to new and existing facilities.</p> <p>This Rule is not met as evidenced by:</p> <ol style="list-style-type: none"> 1. Based on Observation, the facility failed to prevent the possibility of contaminated water from backflowing into the domestic water system. Findings on March 15, 2016: <ol style="list-style-type: none"> a. Spa next to Bedroom 111 - the walk in tub had a shower wand with a hose long enough to reach gray water that did not appear to be equipped with a vacuum breaker to prevent backsiphonage of gray water back into the domestic water lines. b. Exterior Can Wash - the water lines were not equipped with vacuum breaker to prevent backsiphonage of gray water back into the potable water plumbing lines. 2. Based on Observation, the facility failed to provide an environment in accordance with this Rule, by not maintaining the HVAC equipment. Findings on March 15, 2016: <ol style="list-style-type: none"> a. Exterior Fire Wall 300 Wing - the PTAC units cover was laying on the ground. 3. Based on Observation, the Building was not maintained free of hazards, because the portable medical oxygen cylinders were not being properly handled/stored. This could affect all residents, staff and visitors if cylinders fall, breaking their valves, propelling the cylinder and turning it into a dangerous projectile. Findings on March 15, 2016: <ol style="list-style-type: none"> a. 100 Hall - a portable medical oxygen cylinder was stored standing up in the corridor beside the med cart, 4. Based on observation, the building was not maintained in free of obstructions. This would | C 166 | | |

Division of Health Service Regulation

| | | | |
|--|--|---|---|
| STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION | (X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: HAL098027 | (X2) MULTIPLE CONSTRUCTION A. BUILDING: 01 B. WING _____ | (X3) DATE SURVEY COMPLETED 03/15/2016 |
|--|--|---|---|

| | |
|---|---|
| NAME OF PROVIDER OR SUPPLIER WILSON ASSISTED LIVING | STREET ADDRESS, CITY, STATE, ZIP CODE 3501 SENIOR VILLAGE LANE WILSON, NC 27896 |
|---|---|

| (X4) ID PREFIX TAG | SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION) | ID PREFIX TAG | PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY) | (X5) COMPLETE DATE |
|--------------------|---|---------------|---|--------------------|
| C 166 | Continued From page 6 affect all residents, staff and visitors by allowing the possibility that someone could be locked in a room without the means of escape during an emergency. Findings on March 15, 2016: a. Exterior Storage - the door was equipped with a hasp device and padlock along with a locking door knob, b. Left Front Exit - the leaf hits the doorframe making it difficult to open the door, | C 166 | | |
| C 188 | Electrical Outlets in Wet Locations SECTION .0300 - PHYSICAL PLANT 10A NCAC 13F .0310 ELECTRICAL OUTLETS All adult care home electrical outlets in wet locations at sinks, bathrooms and outside of building shall have ground fault interrupters. This Rule is not met as evidenced by: 1. Based on Observation, the facility failed to maintain in a safe manner, the electrical power receptacles in wet areas. This would affect all residents, staff and visitors by not providing ground fault protection to these devices. Findings on March 15, 2016: a. SCU Living/Dining - the ground-fault circuit-interrupter (GFCI) electrical power receptacle near the sink did not trip with a push of the test button and when tested with a circuit tester b. Left Exit 300 Hall - the ground-fault circuit-interrupter (GFCI) electrical power receptacle on the stoop did not trip with a push of the test button and when tested with a circuit teste, | C 188 | | |

Division of Health Service Regulation

| | | | |
|--|--|---|---|
| STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION | (X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: HAL098027 | (X2) MULTIPLE CONSTRUCTION A. BUILDING: 01 B. WING _____ | (X3) DATE SURVEY COMPLETED 03/15/2016 |
|--|--|---|---|

| | |
|---|---|
| NAME OF PROVIDER OR SUPPLIER WILSON ASSISTED LIVING | STREET ADDRESS, CITY, STATE, ZIP CODE 3501 SENIOR VILLAGE LANE WILSON, NC 27896 |
|---|---|

| (X4) ID PREFIX TAG | SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION) | ID PREFIX TAG | PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY) | (X5) COMPLETE DATE |
|--------------------|---|---------------|---|--------------------|
| C 189 | Continued From page 7 | C 189 | | |
| C 189 | <p>Building Equipment Maintained Safe, Operating</p> <p>SECTION .0300 - PHYSICAL PLANT 10A NCAC 13F .0311 OTHER REQUIREMENTS</p> <p>(a) The building and all fire safety, electrical, mechanical, and plumbing equipment in an adult care home shall be maintained in a safe and operating condition.</p> <p>(k) This Rule shall apply to new and existing facilities with the exception of Paragraph (e) which shall not apply to existing facilities.</p> <p>This Rule is not met as evidenced by:</p> <ol style="list-style-type: none"> Based on observation, the Building was not maintain in a safe manner, because the integrity of the fire-resistance-rated corridor ceiling/tunnel construction had holes and gaps in this protected gypsum construction. This could affect all residents, staff and visitors by not providing a safe, fire-resistance-rated exit corridor. Findings on March 15, 2016: a. Front foyer Attic - the tunnel style fire-resistance-rated ceiling construction had been damaged, be repair, Based on observation, the Building was not maintained in a safe and operating condition, because the fire protection equipment was in disrepair. This would affect all residents, staff and visitors by not activating the fire alarm. Findings on March 15, 2016: a. Exterior Storage - the heat collector on the heat detector had been damaged, which could affect the proper operation of the detector, Based on observation, the Building was not maintained in a safe and operating condition, because the exit signs did not work properly or | C 189 | | |

Division of Health Service Regulation

| | | | |
|--|--|---|---|
| STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION | (X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: HAL098027 | (X2) MULTIPLE CONSTRUCTION A. BUILDING: 01 B. WING _____ | (X3) DATE SURVEY COMPLETED 03/15/2016 |
|--|--|---|---|

| | |
|---|---|
| NAME OF PROVIDER OR SUPPLIER WILSON ASSISTED LIVING | STREET ADDRESS, CITY, STATE, ZIP CODE 3501 SENIOR VILLAGE LANE WILSON, NC 27896 |
|---|---|

| (X4) ID PREFIX TAG | SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION) | ID PREFIX TAG | PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY) | (X5) COMPLETE DATE |
|--------------------|---|---------------|---|--------------------|
| C 189 | <p>Continued From page 8</p> <p>relay directional information properly. This would affect all residents, staff and visitors if they could not promptly find their way to an exit during an emergency.</p> <p>Findings on March 15, 2016:</p> <p>a. Left Front Exit - the exit sign did not work on backup power when tested,</p> <p>4. Based on observations, the Building was not maintained in a safe and operating condition, because of holes and gaps through the fire-resistance-rated wall construction invalidated its integrity. This could affect all residents, staff and visitors if smoke/fire is not contained in Room or Compartment of origin.</p> <p>Findings on March 15, 2016:</p> <p>a. Attic Firewall at SCU - there were unprotected cable penetrations through the firewall,</p> <p>b. Attic Firewall at 100 Hall - there were unprotected cable penetrations through the firewall</p> <p>c. Draftstop near Bedroom 106- there a hole through this draftstop,</p> <p>d. Draftstop near Linen Closet - there were holes around pipe penetrations in this draftstop,</p> <p>e. Draftstop near Staff Breakroom - there were cables penetrations in this draftstop,</p> <p>f. Draftstop near Bedroom 306 - there a hole through this draftstop,</p> <p>g. Draftstop near SCU - there were holes around pipe penetrations in this draftstop,</p> <p>5. Based on observation, the Building was not maintained in a safe and operating condition, because the electrical power system was not being operated or maintained safely. This would affect all residents, staff and visitors by allowing unsafe conditions to persist.</p> <p>Findings on March 15, 2016:</p> | C 189 | | |

Division of Health Service Regulation

| | | | |
|--|--|---|---|
| STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION | (X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: HAL098027 | (X2) MULTIPLE CONSTRUCTION A. BUILDING: 01 B. WING _____ | (X3) DATE SURVEY COMPLETED 03/15/2016 |
|--|--|---|---|

| | |
|---|---|
| NAME OF PROVIDER OR SUPPLIER WILSON ASSISTED LIVING | STREET ADDRESS, CITY, STATE, ZIP CODE 3501 SENIOR VILLAGE LANE WILSON, NC 27896 |
|---|---|

| (X4) ID PREFIX TAG | SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION) | ID PREFIX TAG | PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY) | (X5) COMPLETE DATE |
|--------------------|--|---------------|---|--------------------|
|--------------------|--|---------------|---|--------------------|

| | | | | |
|-------|---|-------|--|--|
| C 189 | <p>Continued From page 9</p> <p>a. Electrical Room, panel EP4 - many items are being stored directly in front of the electric panels, preventing quick emergency access to the panel.</p> <p>b. Left of the front door an exterior GFCI electrical outlet was missing its weatherproof cover,</p> <p>c. Left Exit 300 Hall - the exterior GFCI electrical outlet on the stoop was missing its weatherproof cover,</p> <p>d. Shower room next to Bedroom 304 - a lens on a light fixtures had falling down exposing unsupported wires,</p> <p>e. Left Exit 300 Hall - the exterior GFCI electrical outlet's weatherproof cover was missing,</p> <p>f. Attic above SCU - there were multiple open junction box with energized components,</p> <p>g. Bedroom 111 - there was an unapproved multiple plug surge protector without overcurrent protection plugged into an electrical power receptacle. This is not in accordance with the Fire Prevention Code</p> <p>6. Based on observation, the Building was not maintained in a safe and operating condition, because the corridor doors did not resist the passage of smoke due to door leafs not fitting into their frames with acceptable gaps under normal operating conditions. This could affect all residents, staff and visitors if the doors did not contain smoke/fire in the room of origin. Findings on March 15, 2016:</p> <p>a. Bedroom 201 - the corridor door hits the doorframe preventing it from closing and latching without extra force.</p> <p>b. Bedroom 202 - the corridor door hits the doorframe preventing it from closing and latching without extra force.</p> <p>c. SCU Living/Dining Room- the inactive leaf of the double corridor doors had a chain bolt that</p> | C 189 | | |
|-------|---|-------|--|--|

Division of Health Service Regulation

| | | | |
|--|--|---|---|
| STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION | (X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: HAL098027 | (X2) MULTIPLE CONSTRUCTION A. BUILDING: 01 B. WING _____ | (X3) DATE SURVEY COMPLETED 03/15/2016 |
|--|--|---|---|

| | |
|---|---|
| NAME OF PROVIDER OR SUPPLIER WILSON ASSISTED LIVING | STREET ADDRESS, CITY, STATE, ZIP CODE 3501 SENIOR VILLAGE LANE WILSON, NC 27896 |
|---|---|

| (X4) ID PREFIX TAG | SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION) | ID PREFIX TAG | PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY) | (X5) COMPLETE DATE |
|--------------------|---|---------------|---|--------------------|
| C 189 | <p>Continued From page 10</p> <p>had it bolt installed backwards and will not automatically latch into its frame.</p> <p>d. SCU Living/Dining Room- the active leaf of the double corridor doors was missing its top hinge thus has sagged to a point it overlaps the inactive leaf by ¾ inch.</p> <p>e. SCU Living/Dining Room- the single corridor door hits the doorframe preventing it from closing and latching without extra force.</p> <p>f. Bedroom 207 - the corridor door hits the doorframe preventing it from closing and latching without extra force.</p> <p>g. Bedroom 207 - the corridor door was missing its strike plate.</p> <p>7. Based on Observation, the Building was not maintained in a safe and operating condition, because corridor doors are being held open by devices that do not release with a push or pull of the door, preventing the doors from being closed and latched rapidly. This could affect all residents, staff and visitors by not containing smoke and fire in the room of origin. Findings on March 15, 2016: a. Bedroom 209 - the corridor door was blocked open with a bed,</p> <p>8. Based on Observation and interview with Maintenance Tech, the Building was not maintained safe by not providing access to areas for inspection. This deficiency affects all residents, staff and visitors by preventing any deficiency discovered during regular inspections from being corrected. Findings on March 15, 2016: a. Water Heater Room - there was no key onsite to allow access into this area,</p> <p>9. Based on observations, the Building was not maintained in a safe and operating condition,</p> | C 189 | | |

Division of Health Service Regulation

| | | | |
|--|--|---|---|
| STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION | (X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: HAL098027 | (X2) MULTIPLE CONSTRUCTION A. BUILDING: 01 B. WING _____ | (X3) DATE SURVEY COMPLETED 03/15/2016 |
|--|--|---|---|

| | |
|---|---|
| NAME OF PROVIDER OR SUPPLIER WILSON ASSISTED LIVING | STREET ADDRESS, CITY, STATE, ZIP CODE 3501 SENIOR VILLAGE LANE WILSON, NC 27896 |
|---|---|

| (X4) ID PREFIX TAG | SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION) | ID PREFIX TAG | PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY) | (X5) COMPLETE DATE |
|--------------------|--|---------------|---|--------------------|
| C 189 | <p>Continued From page 11</p> <p>because of holes and gaps through the fire-resistance-rated ceiling and wall construction invalidated its integrity. This could affect all residents, staff and visitors if smoke/fire is not contained in Room or compartment of origin. Findings on March 15, 2016:</p> <ul style="list-style-type: none"> a. Oxygen Room - the refrigerant line has a gap around the foam insulation as it penetrates through the fire-resistance-rated ceiling assembly, b. Exterior Storage - the ceiling in the back, there appeared to be an active leak that has started deteriorated the gypsum ceiling, c. Exterior Storage - a three-inch PVC pipe was not protected, penetrated the one-hour fire fire-resistance-rated ceiling. NOTE: PVC pipes larger than 2 inches in diameter require a 'fire collar' or similar system for protection, d. Above Left Front Exit - there was a gap around a cable that penetrated through the fire-resistance-rated ceiling assembly, e. Bedroom 113 - there was a gap around a cable that penetrated through the fire-resistance-rated ceiling assembly, f. Bedroom 111 - there was a gap around a cable that penetrated through the fire-resistance-rated ceiling assembly, g. Above Copier - there was a gap around a cable that penetrated through the fire-resistance-rated ceiling assembly, h. Above Exit 313 - there was a gap around a cable that penetrated through the fire-resistance-rated ceiling assembly i. Front Nurse Station - there was a gap around a cable that penetrated through the fire-resistance-rated ceiling assembly, j. Above Exit 300 - there was a gap around a cable that penetrated through the fire-resistance-rated ceiling assembly, k. Bedroom 306 - there was an open joint | C 189 | | |

Division of Health Service Regulation

| | | | |
|--|--|---|---|
| STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION | (X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: HAL098027 | (X2) MULTIPLE CONSTRUCTION A. BUILDING: 01 B. WING _____ | (X3) DATE SURVEY COMPLETED 03/15/2016 |
|--|--|---|---|

| | |
|---|---|
| NAME OF PROVIDER OR SUPPLIER WILSON ASSISTED LIVING | STREET ADDRESS, CITY, STATE, ZIP CODE 3501 SENIOR VILLAGE LANE WILSON, NC 27896 |
|---|---|

| (X4) ID PREFIX TAG | SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION) | ID PREFIX TAG | PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY) | (X5) COMPLETE DATE |
|--------------------|---|---------------|---|--------------------|
| C 189 | Continued From page 12 between the ceiling and the wall gypsum construction where a fire-resistance-rated ceiling assembly must occur, 10. Based on observation, the facility fire resistance rated components have not been maintained safe and operating condition because the corridor doors are not smoke resisting. This could affect all residents, staff and visitors if the doors did not contain smoke/fire in the room of origin. Findings on March 15, 2016: a. Bedroom 114 - the corridor door hit the doorframe did not latch when closed, | C 189 | | |
| C 199 | Exhaust Ventilation SECTION .0300 - PHYSICAL PLANT 10A NCAC 13F .0311 OTHER REQUIREMENTS (g) The spaces listed in this Paragraph shall be provided with exhaust ventilation at the rate of two cubic feet per minute per square foot. This requirement does not apply to facilities licensed before April 1, 1984, with natural ventilation in these specified spaces: (1) soiled linen storage; (2) soil utility room; (3) bathrooms and toilet rooms; (4) housekeeping closets; and (5) laundry area. (k) This Rule shall apply to new and existing facilities with the exception of Paragraph (e) which shall not apply to existing facilities. This Rule is not met as evidenced by: 1. Based on Observation and testing with a thin plastic sheet, the facility failed to maintain the ventilation system in proper working order. This | C 199 | | |

Division of Health Service Regulation

| | | | |
|--|--|---|---|
| STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION | (X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: HAL098027 | (X2) MULTIPLE CONSTRUCTION A. BUILDING: 01 B. WING _____ | (X3) DATE SURVEY COMPLETED 03/15/2016 |
|--|--|---|---|

| | |
|---|---|
| NAME OF PROVIDER OR SUPPLIER WILSON ASSISTED LIVING | STREET ADDRESS, CITY, STATE, ZIP CODE 3501 SENIOR VILLAGE LANE WILSON, NC 27896 |
|---|---|

| (X4) ID PREFIX TAG | SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION) | ID PREFIX TAG | PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY) | (X5) COMPLETE DATE |
|--------------------|--|---------------|---|--------------------|
| C 199 | Continued From page 13 could affect all residents, staff and visitors by preventing the exhausting of odors. Findings on March 15, 2016: a. Shower room next to Bedroom 111 - the local exhaust ventilation system was running, but did not remove the required air to dissipate the odors, b. Shower room next to Bedroom 107 - the local exhaust ventilation system was running, but did not remove the required air to dissipate the odors, c. Shower room next to Bedroom 304 - the local exhaust ventilation system was running, but did not remove the required air to dissipate the odors, d. Bedroom 311 - the local exhaust ventilation system was running, but did not remove the required air to dissipate the odors, e. Bedroom 308 - the local exhaust ventilation system was running, but did not remove the required air to dissipate the odors, | C 199 | | |