

DEPARTMENT OF HEALTH AND HUMAN SERVICES  
CENTERS FOR MEDICARE & MEDICAID SERVICES

PRINTED: 07/01/2013  
FORM APPROVED  
OMB NO. 0938-0345

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION	(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER:  <b>345009</b>	(X2) MULTIPLE CONSTRUCTION A. BUILDING _____  B. WING _____	(X3) DATE SURVEY COMPLETED  <b>06/27/2013</b>
--	---	--	---


NAME OF PROVIDER OR SUPPLIER  <b>THE OAKS AT MAYVIEW</b>	STREET ADDRESS, CITY, STATE, ZIP CODE <b>513 EAST WHITAKER MILL ROAD RALEIGH, NC 27608</b>
--	---

(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETION DATE
--------------------	--	---------------	---	----------------------

F 000	<p><b>INITIAL COMMENTS</b></p> <p>The facility was found to be in compliance with the Medicare/Medicaid Long Term Care regulations, 42 CFR part 483, subpart B during the recertification survey of 06/27/2013.</p>	F 000		
-------	---	-------	--	--

LABORATORY DIRECTOR'S OR PROVIDER/SUPPLIER REPRESENTATIVE'S SIGNATURE	TITLE	(X6) DATE
---	-------	-----------

Any deficiency statement ending with an asterisk (\*) denotes a deficiency which the institution may be excused from correcting providing it is determined that other safeguards provide sufficient protection to the patients. (See instructions.) Except for nursing homes, the findings stated above are disclosable 90 days following the date of survey whether or not a plan of correction is provided. For nursing homes, the above findings and plans of correction are disclosable 14 days following the date these documents are made available to the facility. If deficiencies are cited, an approved plan of correction is requisite to continued program participation.



DEPARTMENT OF HEALTH AND HUMAN SERVICES  
CENTERS FOR MEDICARE & MEDICAID SERVICES

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER:  345009	(X2) MULTIPLE CONSTRUCTION A. BUILDING 01 - MAIN BUILDING 01  B. WING _____		(X3) DATE SURVEY COMPLETED  07/23/2013
NAME OF PROVIDER OR SUPPLIER  THE OAKS AT MAYVIEW			STREET ADDRESS, CITY, STATE, ZIP CODE 513 EAST WHITAKER MILL ROAD RALEIGH, NC 27608		
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETION DATE	
K 000	INITIAL COMMENTS  This Life Safety Code(LSC) survey was conducted as per The Code of Federal Register at 42CFR 483.70(a); using the 2000 Existing Health Care section of the LSC and its referenced publications. This building 0102 is Type II construction, building 0202 is Type III construction, two story, with a complete automatic sprinkler system. The census was 116.  The deficiencies determined during the survey are as follows:	K 000	K 021  Corrective Action for Accomplished for Identified deficient practice:  Door was repaired on 7/23/2013  Corrective Action for Those with Potential to be affected  All doors in facility checked for proper closure/latching on 7/24/2103.  Systemic Changes to Prevent Deficient Practice  Doors will be checked monthly by Maintenance to ensure compliance utilizing our Building Engines PPM  How will Corrective Action be monitored?  Maintenance director or designee will provide a quarterly report to the QAPI committee for further recommendations  Corrective Action Complete: 7/24/2013		
K 021 SS=D	NFPA 101 LIFE SAFETY CODE STANDARD  Any door in an exit passageway, stairway enclosure, horizontal exit, smoke barrier or hazardous area enclosure is held open only by devices arranged to automatically close all such doors by zone or throughout the facility upon activation of:  a) the required manual fire alarm system;  b) local smoke detectors designed to detect smoke passing through the opening or a required smoke detection system; and  c) the automatic sprinkler system, if installed. 19.2.2.2.6, 7.2.1.8.2  This STANDARD is not met as evidenced by: 42 CFR 483.70(a) By observation on 7/23/13 at approximately noon	K 021			

LABORATORY DIRECTOR'S OR PROVIDER/SUPPLIER REPRESENTATIVE'S SIGNATURE: *August Baker* TITLE: *Administrator* (X6) DATE: *8/4/13*

Any deficiency statement ending with an asterisk (\*) denotes a deficiency which the institution may be excused from correcting providing it is determined that other safeguards provide sufficient protection to the patients. (See Instructions.) Except for nursing homes, the findings stated above are disclosable 90 days following the date of survey whether or not a plan of correction is provided. For nursing homes, the above findings and plans of correction are disclosable 14 days following the date these documents are made available to the facility. If deficiencies are cited, an approved plan of correction is requisite to continued program participation.

DEPARTMENT OF HEALTH AND HUMAN SERVICES  
CENTERS FOR MEDICARE & MEDICAID SERVICES

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER:  345009	(X2) MULTIPLE CONSTRUCTION A. BUILDING 01 - MAIN BUILDING 01  B. WING _____		(X3) DATE SURVEY COMPLETED  07/23/2013
NAME OF PROVIDER OR SUPPLIER  THE OAKS AT MAYVIEW			STREET ADDRESS, CITY, STATE, ZIP CODE 513 EAST WHITAKER MILL ROAD RALEIGH, NC 27608		
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETION DATE	
K 021	Continued From page 1 the following fire/smoke barrier was non-compliant, specific findings include, the door to the fire/smoke wall, near nurses station #4, did not close and latch properly.	K 021	K 038 Corrective Action for Accomplished for Identified deficient practice:		
K 038 SS=D	NFPA 101 LIFE SAFETY CODE STANDARD Exit access is arranged so that exits are readily accessible at all times in accordance with section 7.1. 19.2.1	K 038	Exit lights installed with 2 bulbs to meet illumination requirement on 8/9/2013  Corrective Action for Those with Potential to be affected  All exits lights were checked for proper lighting requirements on 7/30/2013  Systemic Changes to Prevent Deficient Practice  Exit lights will be checked quarterly by the maintenance director or designees through our Building Engines PPM to ensure proper illumination. Any identified lights out of compliance will be corrected immediately.		
K 050 SS=D	This STANDARD is not met as evidenced by: 42 CFR 483.70(a) By observation on 7/23/13 at approximately noon the following exit discharge illumination was non-compliant, specific findings include, a single bulb fixture at the 800 hall and also the riser room exits. Lighting must be arranged to provide light from the exit discharge leading to the public way (parking lot). The walking surfaces within the exit discharge shall be illuminated to values of at least 1 ft-candle measured at the floor. Failure of any single lighting unit does not result in an illumination level of less than 0.2 ft-candles in any designated area. NFPA 101 7.8.1.1, 7.8.1.3, and 7.8.1.4. NFPA 101 LIFE SAFETY CODE STANDARD Fire drills are held at unexpected times under varying conditions, at least quarterly on each shift. The staff is familiar with procedures and is aware that drills are part of established routine. Responsibility for planning and conducting drills is assigned only to competent persons who are qualified to exercise leadership. Where drills are	K 050	How will Corrective Action be monitored?  Maintenance director or designee will provide a quarterly report to the QAPI committee for further recommendations  Corrective Action Complete: 8/10/2013		

PRINTED: 07/26/2013  
FORM APPROVED  
OMB NO. 0938-0391

DEPARTMENT OF HEALTH AND HUMAN SERVICES  
CENTERS FOR MEDICARE & MEDICAID SERVICES

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER:  345009	(X2) MULTIPLE CONSTRUCTION A. BUILDING 01 - MAIN BUILDING 01  B. WING _____	(X3) DATE SURVEY COMPLETED  07/23/2013
NAME OF PROVIDER OR SUPPLIER  THE OAKS AT MAYVIEW			STREET ADDRESS, CITY STATE, ZIP CODE 513 EAST WHITAKER MILL ROAD RALEIGH, NC 27608	
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETION DATE
K 050	Continued From page 2 conducted between 9 PM and 6 AM a coded announcement may be used instead of audible alarms. 19.7.1.2	K 050	K 050  Corrective Action for Accomplished for Identified deficient practice:  A fire drill for the specified time period of 9 pm to 6 am was conducted on 7/ 24/13	
K 052 SS=D	This STANDARD is not met as evidenced by: 42 CFR 483.70(a) By observation on 7/23/13 at approximately noon the following fire drills were non-compliant, specific findings include, documentation indicated less than the required number of drills were held on third shift of 1st quarter 2013. NFPA 101 LIFE SAFETY CODE STANDARD  A fire alarm system required for life safety is installed, tested, and maintained in accordance with NFPA 70 National Electrical Code and NFPA 72. The system has an approved maintenance and testing program complying with applicable requirements of NFPA 70 and 72. 9.6.1.4  This STANDARD is not met as evidenced by: 42 CFR 483.70(a) By observation on 7/23/13 at approximately noon the following fire alarm system was non-compliant, specific findings include:  A. The Visual/Audible (VA) device, located at nurses station #4, did not function while the	K 052	Corrective Action for Those with Potential to be affected  Maintenance Director or designee will conduct fire drills according to regulation. Fire drill reports will be signed by the Administrator or designee to ensure compliance  Systemic Changes to Prevent Deficient Practice  As stated above, Administrator or designee will sign monthly fire drill reports to ensure compliance.  How will Corrective Action be monitored?  Maintenance director or designee will provide a monthly report to the QAPI committee for further recommendations  Corrective Action Complete: 8/2/2013	

PRINTED: 07/26/2013  
FORM APPROVED  
OMB NO. 0938-0391

DEPARTMENT OF HEALTH AND HUMAN SERVICES  
CENTERS FOR MEDICARE & MEDICAID SERVICES

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		(K1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER:  345009	(X2) MULTIPLE CONSTRUCTION A. BUILDING 01 - MAIN BUILDING 01  B. WING _____	(X3) DATE SURVEY COMPLETED  07/23/2013
NAME OF PROVIDER OR SUPPLIER  THE OAKS AT MAYVIEW			STREET ADDRESS, CITY, STATE, ZIP CODE 513 EAST WHITAKER MILL ROAD RALEIGH, NC 27608	
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETION DATE
K 052	Continued From page 3 building fire alarm control panel was on battery back up power.	K 052	K 052	
K 067 SS=D	B. There was not a VA device, located in the smoke compartment with the beauty shop, near nurses station #4. This was also noted on the Fire Marshall's report.  NFPA 101 LIFE SAFETY CODE STANDARD Heating, ventilating, and air conditioning comply with the provisions of section 9.2 and are installed in accordance with the manufacturer's specifications. 19.5.2.1, 9.2, NFPA 90A, 19.5.2.2  This STANDARD is not met as evidenced by: 42 CFR 483.70(a) By observation on 7/23/13 at approximately noon the following Heating, Ventilating, and Air Conditioning system (HVAC) was non-compliant, specific findings include:  A. The new carrier ductless HVAC system at nurses station #4 and #2 did not shut down with fire alarm activation.  B. There was not an emergency shut down switch located at a readily observed station for the new carrier ductless HVAC system at nurses station #4 and #2.  C. The kitchen door did not close and latch tightly in it's frame. At the time of the survey the kitchen was experiencing a sever negative pressure.	K 067	<p>Corrective Action for Accomplished for Identified deficient practice:</p> <p>A visual / audible device on Station 4 is functioning and new battery installed on 8/2/2013 by BFPE.</p> <p>A visual / audible device will be installed by 8/9/2013 in the smoke compartment near the beauty shop by BFPE.</p> <p>Corrective Action for Those with Potential to be affected</p> <p>All visual / audible devices were checked to ensure functioning on 7/25/2013</p> <p>Systemic Changes to Prevent Deficient Practice</p> <p>Visual/Audible devices will be checked quarterly by Maintenance director or designee using Building Engines PPM</p> <p>How will Corrective Action be monitored?</p> <p>Maintenance director or designee will provide a quarterly report to the QAPI committee for further recommendations</p> <p>Corrective Action Complete: 8/10/2013</p>	

DEPARTMENT OF HEALTH AND HUMAN SERVICES  
CENTERS FOR MEDICARE & MEDICAID SERVICES

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER:  345009	(X2) MULTIPLE CONSTRUCTION A. BUILDING 01 - MAIN BUILDING 01  B. WING _____	(X3) DATE SURVEY COMPLETED  07/23/2013
NAME OF PROVIDER OR SUPPLIER  THE OAKS AT MAYVIEW			STREET ADDRESS, CITY, STATE, ZIP CODE 513 EAST WHITAKER MILL ROAD RALEIGH, NC 27608	
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETION DATE
K 067	Continued From page 4 NFPA 96 (Standard for Ventilation Control and Fire Protection of Commercial Cooking Operations 1998 Edition) Section 5-3* Replacement Air. - " Replacement air quantity shall be adequate to prevent negative pressures in the commercial cooking area(s) from exceeding 0.02 in. water column (4.98 kPa). "	K 067	K 067  Corrective Action for Accomplished for Identified deficient practice:  Carrier HVAC units were wired into Fire System to automatically shut off during Fire Alarm on 8/9/2013	
K 130 SS=D	NFPA 101 MISCELLANEOUS  OTHER LSC DEFICIENCY NOT ON 2786  This STANDARD is not met as evidenced by: 42 CFR 483.70(a) By observation on 7/23/13 at approximately noon the following items were non-compliant, specific findings include:  A. The combustion area above and behind the gas dryers including the sprinkler head was filled with lint/dust.  B. Special locking was being installed in the facility. It was discussed that plan review and approval from licensure would need to be obtained. Request approval in writing for proper installation.	K 130	Emergency shut off switch installed on by BFPE by 8/9/2013  Kitchen negative pressure corrected on 7.30/13.  Corrective Action for Those with Potential to be affected  All air handler units were identified to ensure they are connected to the fire system to automatically shut off. on 7/31/232013  No other areas identified to need emergency cut off switch  NO other areas identified with negative pressure.	
K 147 SS=D	NFPA 101 LIFE SAFETY CODE STANDARD  Electrical wiring and equipment is in accordance with NFPA 70, National Electrical Code. 9.1.2  This STANDARD is not met as evidenced by: 42 CFR 483.70(a)	K 147	Systemic Changes to Prevent Deficient Practice  Air handler units including Carrier HVAC units will be checked during Monthly fire drills to ensure functioning and included on monthly fire drill report.	

DEPARTMENT OF HEALTH AND HUMAN SERVICES  
CENTERS FOR MEDICARE & MEDICAID SERVICES

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER:  345009	(X2) MULTIPLE CONSTRUCTION A. BUILDING 01 - MAIN BUILDING 01  B. WING _____	(X3) DATE SURVEY COMPLETED  07/23/2013
NAME OF PROVIDER OR SUPPLIER  THE OAKS AT MAYVIEW			STREET ADDRESS, CITY, STATE, ZIP CODE 513 EAST WHITAKER MILL ROAD RALEIGH, NC 27608	
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETION DATE
K 147	Continued From page 5 By observation on 7/23/13 at approximately noon the following electrical item was non-compliant, specific findings include, the lights on the Automatic Transfer Switch (ATS) showing normal and emergency power were not operational.	K 147	Negative pressure identified in Kitchen will be checked monthly by Maintenance Director or designee through Building Engines PPM.  How will Corrective Action be Monitored:  Maintenance director or designee will provide a monthly report to the QAPI committee for further recommendations.  Corrective Action Complete: 8/10/2013  K 130  Corrective Action for Accomplished for Identified deficient practice:  The combustion area above and behind the gas dryers including the sprinkler head was cleaned of lint and dust on 7/25/2013  Requesting a waiver for the special locking plan review.  Corrective Action for Those with Potential to be affected  Sprinkler heads in building were checked for dust and lint on 7/30/2013  Systemic Changes to Prevent Deficient Practice:	

PRINTED: 07/26/2013  
FORM APPROVED  
OMB NO. 0938-0391

DEPARTMENT OF HEALTH AND HUMAN SERVICES  
CENTERS FOR MEDICARE & MEDICAID SERVICES

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER:  345009	(X2) MULTIPLE CONSTRUCTION A. BUILDING 02 - BUILDING 2  B. WING _____	(X3) DATE SURVEY COMPLETED  07/23/2013
NAME OF PROVIDER OR SUPPLIER  THE OAKS AT MAYVIEW			STREET ADDRESS, CITY, STATE, ZIP CODE 813 EAST WHITAKER MILL ROAD RALEIGH, NC 27608	
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X6) COMPLETION DATE
K 000	INITIAL COMMENTS  There were no Life Safety Code Deficiencies noted at time of survey.	K 000	<p>Sprinkler heads will be checked quarterly by the Maintenance Director or designee through Building Engines PPM</p> <p>Combustion area around gas dryers will be checked monthly by the Maintenance Director or Designee through Building Engines PPM.</p> <p>How will Corrective Action be Monitored:</p> <p>Maintenance director or designee will provide a quarterly report to the QAPI committee for further recommendations for Sprinkler heads and monthly for the Gas Dryers</p> <p>Corrective Action Complete: 8/10/2013</p> <p>K 147</p> <p>Corrective Action for Accomplished for Identified deficient practice:</p> <p>Light on the Automatic Transfer Switch was corrected on 8/1/2013.</p> <p>Corrective Action for Those with Potential to be affected</p> <p>No other areas identified upon our inspection of facility on 7/26/2013.</p>	

LABORATORY DIRECTOR'S OR PROVIDER/SUPPLIER REPRESENTATIVE'S SIGNATURE

*Angela A. Poole*

TITLE

*Administrator*

(X6) DATE

*8/4/13*

Any deficiency statement ending with an asterisk (\*) denotes a deficiency which the institution may be excused from correcting providing it is determined that other safeguards provide sufficient protection to the patients. (See Instructions.) Except for nursing homes, the findings stated above are disclosable 90 days following the date of survey whether or not a plan of correction is provided. For nursing homes, the above findings and plans of correction are disclosable 14 days following the date these documents are made available to the facility. If deficiencies are cited, an approved plan of correction is requisite to continued program participation.

*DPW*

**Systemic Changes to Prevent Deficient Practice**

Automatic Transfer Switch light will be checked monthly during Generator testing by the Maintenance Director or Designee.

**How will Corrective Action be Monitored:**

Maintenance director or designee will provide a quarterly report to the QAPI committee for further recommendations.

**Corrective Action Complete: 8/10/2013**