

CONFIDENTIAL / CONFIDENTIAL

TO: DHSR Construction

FAX: (919) 733-6592

FROM: Keasha Houston Maddox

DATE: 5/17/2016

RE:

PAGES: 3 including cover

NOTE:

URGENT

PER REVIEW

PLEASE REPLY

Should there be problems with the transmission of this material, please call the number above. This fax is intended only for the use of the addressee and may contain confidential information. If you are not the intended recipient, you are notified that any dissemination, distribution, or copying is strictly prohibited. If you have received this fax in error, please notify us immediately by telephone and return it to us at the given address via the United States Postal Service. We will reimburse you any costs you incur in notifying and returning it to us. Thank you.

Division of Health Service Regulation

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION	(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: FCL040009	(X2) MULTIPLE CONSTRUCTION A. BUILDING: 01 B. WING: _____	(X3) DATE SURVEY COMPLETED 04/22/2016
--	--	--	---

NAME OF PROVIDER OR SUPPLIER SOZO FAMILY CARE HOME	STREET ADDRESS, CITY, STATE, ZIP CODE 2757 MEWBORN CHURCH ROAD SNOW HILL, NC 28580
--	--

(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETE DATE
--------------------	--	---------------	---	--------------------

C 000 Initial Comments C 000

Report by Rick Benton

DHSR Construction Section conducted a Biennial Survey on April 22, 2016 from 1:00pm to 2:15pm at the above referenced facility. DHSR records indicate the home was first licensed on 01/24/2012 as a Family Care Home for six (6) ambulatory Residents (able to evacuate and respond without any physical or verbal assistance during a fire or other emergency). Based on this we are requiring the home to be in compliance with the following: the 2005 Rules 10A NCAC 13G for Family Care Homes, and the 2009 Edition of the North Carolina State Building Code - Section 425.2 - Residential Care Homes.

At the time of our visit, we cited deficiencies that require an acceptable plan of correction. They are as follows:

C 174 Building Equipment Maintained Safe, Operating C 174

SECTION .0300 - THE BUILDING
10A NCAC 13G .0317 BUILDING SERVICE EQUIPMENT

(a) The building and all fire safety, electrical, mechanical, and plumbing equipment in a family care home shall be maintained in a safe and operating condition.


(j) This Rule shall apply to new and existing family care homes.

This Rule is not met as evidenced by:
1) During the survey of all of the interior rooms in the home, the following deficiencies were observed:
a) The window blinds were damaged in the master bedroom windows, the window in bedroom 2, the window in bedroom 3 and in the

All blinds will be Replaced

5/17/16

Division of Health Service Regulation
LABORATORY DIRECTOR'S OR PROVIDER/SUPPLIER REPRESENTATIVE'S SIGNATURE

TITLE


(X6) DATE
5/17/16

Division of Health Service Regulation

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION	(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: FCL040009	(X2) MULTIPLE CONSTRUCTION A. BUILDING: 01 B. WING: _____	(X3) DATE SURVEY COMPLETED 04/22/2016
--	--	---	---

NAME OF PROVIDER OR SUPPLIER SOZO FAMILY CARE HOME	STREET ADDRESS, CITY, STATE, ZIP CODE 2757 MEWBORN CHURCH ROAD SNOW HILL, NC 28580
--	--

(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETE DATE
--------------------	--	---------------	---	--------------------

C 174	<p>Continued From page 1</p> <p>dining room.</p> <p>b) All of the windows did operate, but they were difficult to raise to the full required height.</p> <p>c) There was no globe attached to the light fixture in bedroom 4.</p> <p>d) The dresser in bedroom 2 was damaged. Contact a qualified technician to make the necessary repairs. Arrange to have the damage dresser repaired or replaced. Provide to our office all supporting documents that will verify the completed work.</p> <p>2) During the survey of the outside of the home, the following deficiency was observed:</p> <p>a) The exterior siding appears dirty and has some mildew buildup in several locations. Contact a qualified technician to make the necessary repairs. Provide to our office all supporting documents that will verify the completed work.</p> <p>During the survey of the bathroom 2, the following deficiency was observed:</p> <p>a) The grout on bathtub wall tile appeared to be stained. Contact a qualified technician to make the necessary repairs. Provide to our office all supporting documents that will verify the completed work.</p>	C 174	<p>b) will provide silicone to each window so it can operate properly 5/17</p> <p>c) Globe will be replaced</p> <p>D) Dresser has been removed</p> <p>Contacting individual to pressure wash exterior siding outside the home 5/17</p> <p>bathtub wall tile will be deep clean to remove grout. 5/17</p>	
-------	---	-------	--	--

