

Division of Health Service Regulation

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION	(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER:  <b>HAL049028</b>	(X2) MULTIPLE CONSTRUCTION A. BUILDING: <b>01</b>  B. WING _____	(X3) DATE SURVEY COMPLETED  <b>R</b> <b>01/26/2016</b>
--	--	---	---

NAME OF PROVIDER OR SUPPLIER  <b>AURORA OF STATESVILLE</b>	STREET ADDRESS, CITY, STATE, ZIP CODE <b>1902 ORA DRIVE STATESVILLE, NC 28625</b>
--	--

(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETE DATE
{C 000}	Initial Comments  Report of a Follow-Up Construction Survey by Ed Miller on January 26, 2016.  The following deficiencies cited during the Biennial Construction Survey, have not been satisfactorily corrected and will require a new Plan of Correction. A new citation was added	{C 000}		
{C 101}	Existing Licensed Fac- No less than '71 Rules  SECTION .0300 - PHYSICAL PLANT 10A NCAC 13F .0301 APPLICATION OF PHYSICAL PLANT REQUIREMENTS The physical plant requirements for each adult care home shall be applied as follows: (2) Except where otherwise specified, existing licensed facilities or portions of existing licensed facilities shall meet licensure and code requirements in effect at the time of construction, change in service or bed count, addition, renovation, or alteration; however in no case shall the requirements for any licensed facility where no addition or renovation has been made, be less than those requirements found in the 1971 "Minimum and Desired Standards and Regulations" for "Homes for the Aged and Infirm", copies of which are available at the Division of Health Service Regulation at no cost;  This Rule is not met as evidenced by: 1-Based on observation, the facility does not meet the Building Code requirements for components of the HVAC distribution system which penetrate the one-hour roof/ceiling assembly. This could affect all residents and staff in the event that fire and/or smoke is not contained in a room or compartment of origin.	{C 101}		

Division of Health Service Regulation  
LABORATORY DIRECTOR'S OR PROVIDER/SUPPLIER REPRESENTATIVE'S SIGNATURE \_\_\_\_\_ TITLE \_\_\_\_\_ (X6) DATE \_\_\_\_\_

Division of Health Service Regulation

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION	(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER:  <b>HAL049028</b>	(X2) MULTIPLE CONSTRUCTION A. BUILDING: <b>01</b>  B. WING _____	(X3) DATE SURVEY COMPLETED  <b>R</b> <b>01/26/2016</b>
--	--	---	---

NAME OF PROVIDER OR SUPPLIER  <b>AURORA OF STATESVILLE</b>	STREET ADDRESS, CITY, STATE, ZIP CODE <b>1902 ORA DRIVE STATESVILLE, NC 28625</b>
--	--

(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETE DATE
{C 101}	Continued From page 1  Findings on January 26, 2016: The ceiling HVAC supply diffusers located in the Kitchen, that penetrate the one-hour roof/ceiling construction, do not have any identified fire protection components in place.	{C 101}		
C 150	Corridors-Free of equipment and Obstructions  SECTION .0300 - PHYSICAL PLANT 10A NCAC 13F .0305 PHYSICAL ENVIRONMENT (g) The requirements for corridors are: (4) Corridors shall be free of all equipment and other obstructions.  This Rule is not met as evidenced by: 1. Based on observation, the Building was not maintained in a safe manner by not maintaining a clear unobstructed exit path in the corridors to the outside. NC State Building Code requires a six-foot wide corridor. This would affect all residents, staff and visitors by obstructing egress during an emergency. Findings on January 26, 2016: a. At the inspection of the Front Corridor and Main Corridor there was a reception desk with chair, that decreased the required six foot width to four feet.	C 150		
{C 166}	Housekeeping-Maintained Free of Hazards  SECTION .0300 - PHYSICAL PLANT 10A NCAC 13F .0306 HOUSEKEEPING AND FURNISHINGS (a) Adult care homes shall: (5) be maintained in an uncluttered, clean and orderly manner, free of all obstructions and hazards; (e) This Rule shall apply to new and existing	{C 166}		

Division of Health Service Regulation

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION	(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER:  <b>HAL049028</b>	(X2) MULTIPLE CONSTRUCTION A. BUILDING: <b>01</b>  B. WING _____	(X3) DATE SURVEY COMPLETED  <b>R</b> <b>01/26/2016</b>
--	--	---	---

NAME OF PROVIDER OR SUPPLIER  <b>AURORA OF STATESVILLE</b>	STREET ADDRESS, CITY, STATE, ZIP CODE <b>1902 ORA DRIVE STATESVILLE, NC 28625</b>
--	--

(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETE DATE
{C 166}	Continued From page 2  facilities.  This Rule is not met as evidenced by: 2-Based on Observation, the facility failed to provide an environment in accordance with this Rule by not providing ventilation where odors are generated. This could affect residents and staff by subjecting them to house-keeping odors.  Findings on January 26, 2016: The exhaust fans were not operational for mechanical ventilation at the following locations: (b) "A" Hall Chart Room	{C 166}		
{C 199}	Exhaust Ventilation  SECTION .0300 - PHYSICAL PLANT 10A NCAC 13F .0311 OTHER REQUIREMENTS (g) The spaces listed in this Paragraph shall be provided with exhaust ventilation at the rate of two cubic feet per minute per square foot. This requirement does not apply to facilities licensed before April 1, 1984, with natural ventilation in these specified spaces: (1) soiled linen storage; (2) soil utility room; (3) bathrooms and toilet rooms; (4) housekeeping closets; and (5) laundry area. (k) This Rule shall apply to new and existing facilities with the exception of Paragraph (e) which shall not apply to existing facilities.  This Rule is not met as evidenced by: 1-Based on Observation, the facility failed to provide an environment in accordance with this Rule by not providing ventilation where odors are generated. This could affect residents and staff	{C 199}		

Division of Health Service Regulation

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION	(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER:  <b>HAL049028</b>	(X2) MULTIPLE CONSTRUCTION A. BUILDING: <b>01</b>  B. WING _____	(X3) DATE SURVEY COMPLETED  <b>R</b> <b>01/26/2016</b>
--	--	---	---

NAME OF PROVIDER OR SUPPLIER  <b>AURORA OF STATESVILLE</b>	STREET ADDRESS, CITY, STATE, ZIP CODE <b>1902 ORA DRIVE</b> <b>STATESVILLE, NC 28625</b>
--	--

(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETE DATE
{C 199}	Continued From page 3  by subjecting them to house-keeping odors.  Findings on January 26, 2016: No mechanical exhaust ventilation has been provided in the "A" Hall Spa Shower Room.	{C 199}		