

Division of Health Service Regulation

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION	(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: FCL016019	(X2) MULTIPLE CONSTRUCTION A. BUILDING: 01 B. WING _____	(X3) DATE SURVEY COMPLETED 03/18/2016
--	--	---	---

NAME OF PROVIDER OR SUPPLIER SEA COAST FCH	STREET ADDRESS, CITY, STATE, ZIP CODE 107 GRAHAM ROAD BEAUFORT, NC 28516
--	--

(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETE DATE
C 000	<p>Initial Comments</p> <p>Report by Suzanna Fay</p> <p>DHSR Construction Section conducted a Biennial Survey on March 18, 2016 from 11:00 AM to 12:08 PM at the above referenced facility. DHSR records indicate the home was first licensed on December 18, 1991 as a Family Care Home for six ambulatory Residents (able to evacuate and respond without any physical or verbal assistance during a fire or other emergency.) Based on this information we are requiring the home to maintain compliance with the following: the 1991 Family Care Homes Minimum Standards and Regulations, applicable portions of the 2005 Rules 10A NCAC 13G for Family Care Homes and the 1991 North Carolina State Building Code - Section 513.1, Exception 1 - Residential Care Facilities.</p> <p>At the time of our visit, we cited deficiencies that require an acceptable plan of correction. They are as follows:</p>	C 000		
C 174	<p>Building Equipment Maintained Safe, Operating</p> <p>SECTION .0300 - THE BUILDING 10A NCAC 13G .0317 BUILDING SERVICE EQUIPMENT (a) The building and all fire safety, electrical, mechanical, and plumbing equipment in a family care home shall be maintained in a safe and operating condition. (j) This Rule shall apply to new and existing family care homes.</p> <p>This Rule is not met as evidenced by: 1. Observations revealed that the flaps for the dryer back flow preventor had broken off. Have a qualified technician repair or replace the back</p>	C 174		

Division of Health Service Regulation
LABORATORY DIRECTOR'S OR PROVIDER/SUPPLIER REPRESENTATIVE'S SIGNATURE _____ TITLE _____ (X6) DATE _____

Division of Health Service Regulation

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION	(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: FCL016019	(X2) MULTIPLE CONSTRUCTION A. BUILDING: 01 B. WING _____	(X3) DATE SURVEY COMPLETED 03/18/2016
--	--	---	---

NAME OF PROVIDER OR SUPPLIER SEA COAST FCH	STREET ADDRESS, CITY, STATE, ZIP CODE 107 GRAHAM ROAD BEAUFORT, NC 28516
--	--

(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETE DATE
C 174	Continued From page 1 flow preventor. Provide documentation of the repairs in the form of photos, receipts or work orders. 2. Observations revealed that the exterior GFCI outlet outside of Bedroom #2 did not have a protective cover. Install a protective cover. Provide documentation of the repairs in the form of photos or receipts.	C 174		
C 143	Outside Exits-Locks Single Hand Motion IV. The Building C. Physical Environment (10 NCAC 42C .2201) 8. Outside Entrances/Exits (10 NCAC 42C .2209) d. All exit doors locks must be easily operable, by a single hand motion, from the inside at all times without keys. (This limits each door to one locking device which meets the criteria set forth in this standard.) This Rule is not met as evidenced by: 1. Observations revealed that the storm door at the living room exit had a deadbolt latch. Have a qualified technician remove or disable the deadbolt. Provide documentation of the repairs in the form of photos, receipts or work orders.	C 143		
C 151	Outside Premises-Walkways Illuminated IV. The Building C. Physical Environment (10 NCAC 42C .2201)	C 151		

Division of Health Service Regulation

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION	(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: FCL016019	(X2) MULTIPLE CONSTRUCTION A. BUILDING: 01 B. WING _____	(X3) DATE SURVEY COMPLETED 03/18/2016
--	--	---	---

NAME OF PROVIDER OR SUPPLIER SEA COAST FCH	STREET ADDRESS, CITY, STATE, ZIP CODE 107 GRAHAM ROAD BEAUFORT, NC 28516
--	--

(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETE DATE
C 151	Continued From page 2 11. Outside Premises (10 NCAC 42C .2215) c. Outdoor walkways and drives must be illuminated by no less than five foot candle of light at ground level. This Rule is not met as evidenced by: 1. Observations revealed that the light at the back porch was out. Install a bulb and make sure the light is working to provide a well lit exit. Provide documentation of the repairs in the form of photos or receipts.	C 151		
C 163	Fire Safety-Fire Rehearsals IV. The Building E. Fire Safety Requirements (10 NCAC 42C .2213) 6. There must be at least four rehearsals of the fire and disaster plan each year. Records of rehearsals are to be maintained and copies furnished to the county department of social services annually. The records must include the date and time of the rehearsals, staff members present, and a short description of what the rehearsal involved. This Rule is not met as evidenced by: 1. Review of records revealed that the Owner was unable to locate the fire and disaster drill logs. Provide a copy of the last twelve months of fire and disaster drills to DHSR/Construction Section with your signed Plan of Corrections.	C 163		