

Division of Health Service Regulation

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION	(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: FCL011298	(X2) MULTIPLE CONSTRUCTION A. BUILDING: 01 B. WING _____	(X3) DATE SURVEY COMPLETED 12/02/2015
--	--	---	---

NAME OF PROVIDER OR SUPPLIER HAYWOOD HEIGHTS FAMILY CARE HOME	STREET ADDRESS, CITY, STATE, ZIP CODE 17 EUCLID BOULEVARD ASHEVILLE, NC 28806
---	---

(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETE DATE
--------------------	--	---------------	---	--------------------

C 000	<p>Initial Comments</p> <p>Report by Glenn Hoppin</p> <p>DHSR Construction Section conducted a Complaint Survey on December 02, 2015 from 4:30pm until 6:00pm at the above referenced facility. DHSR records indicate the home was first licensed on July 13, 1995 as a Family Care Home for six Residents with no more than three who are non-ambulatory (un-able to evacuate and respond without any physical or verbal assistance during a fire or other emergency). Based on this information we are requiring the home to maintain compliance with the following: the 1992 "Rules for Family Care Homes Minimum and Desired Standards and Regulations", the applicable portions of the 2005 Rules 10A NCAC 13G for Family Care Homes, and the 1991 (95 Rev) North Carolina State Building Code - Section 514.2 - Small Residential Care Facilities.</p> <p>At the time of our visit, we cited deficiencies that require an acceptable plan of correction. They are as follows:</p>	C 000		
C 153	<p>Houskeeping And Furnishings-Clean, Repaired</p> <p>SECTION .0300 - THE BUILDING 10A NCAC 13G .0315 HOUSEKEEPING AND FURNISHINGS</p> <p>(a) Each family care home shall:</p> <p>(1) have walls, ceilings, and floors or floor coverings kept clean and in good repair;</p> <p>(2) have no chronic unpleasant odors;</p> <p>(3) have furniture clean and in good repair;</p> <p>(e) This Rule shall apply to new and existing homes.</p> <p>This Rule is not met as evidenced by: The facility has a bed bug infestation. The facility</p>	C 153		

Division of Health Service Regulation
LABORATORY DIRECTOR'S OR PROVIDER/SUPPLIER REPRESENTATIVE'S SIGNATURE _____ TITLE _____ (X6) DATE _____

Division of Health Service Regulation

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION	(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: FCL011298	(X2) MULTIPLE CONSTRUCTION A. BUILDING: 01 B. WING _____	(X3) DATE SURVEY COMPLETED 12/02/2015
--	--	---	---

NAME OF PROVIDER OR SUPPLIER HAYWOOD HEIGHTS FAMILY CARE HOME	STREET ADDRESS, CITY, STATE, ZIP CODE 17 EUCLID BOULEVARD ASHEVILLE, NC 28806
---	---

(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETE DATE
C 153	<p>Continued From page 1</p> <p>is in violation of sanitation regulations in accordance with DENR Form 2094 Section 14 VERMIN CONTROL/PREMISES: Outside openings effectively screened or otherwise protected against entrance of flying insects, and flying insects absent; effective control of rodents and other vermin; approved pesticides properly used; premises neat, clean, drained and free of litter and vermin harborages and breeding areas.</p> <p>Licensed pest control contractors are currently treating the facility for bedbugs. Continue the treatment plan as recommended by the pest control contractor. In addition to the current plan, install passive bedbug traps on all beds. Move all beds away from walls and keep all linens and laundry away from the floor. Contact DHSR Construction when all the required items are in place and a follow up survey will be performed.</p>	C 153		